

Report for:

Mr. Quality Control EMLab P&K (QA) 1150 Bayhill Drive Suite 100 San Bruno, CA 94066

Eurofins EPK Built Environment Testing, LLC

Regarding: Project: Sample Report EML ID: 1024877

Approved by:

Technical Manager Murali Putty

Murali R Puty

Dates of Analysis: Culturable air fungi (Incl. Asp spp.): 02-08-2013

Service SOPs: Culturable air fungi (Incl. Asp spp.) (EM-MY-S-1043) AIHA-LAP, LLC accredited service, Lab ID #102856

All samples were received in acceptable condition unless noted in the Report Comments portion in the body of the report. Due to the nature of the analyses performed, field blank correction of results is not applied. The results relate only to the samples as received and tested. Information supplied by the client which can affect the validity of results: sample air volume.

Eurofins EPK Built Environment Testing, LLC ("the Company"), a member of the Eurofins Built Environment Testing group of companies, shall have no liability to the client or the client's customer with respect to decisions or recommendations made, actions taken or courses of conduct implemented by either the client or the client's customer as a result of or based upon the Test Results. In no event shall the Company be liable to the client with respect to the Test Results except for the Company's own willful misconduct or gross negligence nor shall the Company be liable for incidental or consequential damages or lost profits or revenues to the fullest extent such liability may be disclaimed by law, even if the Company has been advised of the possibility of such damages, lost profits or lost revenues. In no event shall the Company's liability with respect to the Test Results exceed the amount paid to the Company by the client therefor.

Eurofins EPK Built Environment Testing, LLC's LabServe® reporting system includes automated fail-safes to ensure that all AIHA-LAP, LLC quality requirements are met and notifications are added to reports when any quality steps remain pending.

Eurofins EPK Built Environment Testing, LLC

EMLab ID: 1024877, Page 2 of 2

111 Anza Boulevard, Suite 122, Burlingame, CA 94010 (800) 651-4802 www.eurofinsus.com/Built

Client: EMLab P&K (QA) C/O: Mr. Quality Control Re: Sample Report Date of Sampling: 02-01-2013 Date of Receipt: 02-01-2013 Date of Report: 02-08-2013

CULTURABLE AIR FUNGI REPORT

Lab ID-Version‡ Location Analysis Date	Air vol. (L)	Medium	Dilution Factor	Fungal ID	Colony Counts	CFU/m3	%
4590863-1	85	MEA	N/A	Alternaria	1	12	3
1				Aspergillus niger	3	35	8
Outside Reference				Aspergillus versicolor	1	12	3
Analysis date:				Basidiomycetes	1	12	3
02/08/2013				Cladosporium	26	320	68
				Non-sporulating fungi	5	59	13
				Penicillium	2	24	5
						§ Total: 470	
Comments:							
4590864-1	85	MEA	N/A	Aspergillus niger	1	12	5
2				Cladosporium	13	150	62
				Non-sporulating fungi	1	12	5
Analysis date:				Penicillium	5	59	24
02/08/2013				Yeasts	1	12	5
						§ Total: 250	
Comments:							
4590865-1	85	MEA	N/A	Acremonium	1	12	2
3				Aspergillus terreus	2	24	4
				Cladosporium	9	110	18
Analysis date: 02/08/2013				Penicillium	36	450	76
						§ Total: 590	
Comments:			_				

The limit of detection is 1 raw count per volume of air sampled. The analytical sensitivity is 1 raw count/volume x the positive hole correction factor.

[‡] A "Version" indicated by -"x" after the Lab ID# with a value greater than 1 indicates a sample with amended data. The revision number is reflected by the value of "x".

[§] Total has been rounded to two significant figures to reflect analytical precision.